



## USB Driver Installation

### *OS: Windows XP and Windows 2000*

**STEP 1.** To install the driver, run setup.exe, located at the directory \DISK1 on the installation media. This will install all the necessary files in the default directory C:\Program Files\Texas Instruments. The progress is shown by the following windows.




Figure 1 - Driver Installation Progress




Figure 2 - License agreement

Although the drivers have not been certified by Microsoft WHQL, TI testing has shown that they pass the HCT test suite used by the WHQL labs. TI plans to obtain official certification in 2Q2005. Contact TI for the latest information.

Because the drivers are not yet certified, the software installation warnings shown in Figure 3 and Figure 4 are generated. The reason two warnings are generated is that the driver is composed of two separate modules, one for the USB functionality and one for the serial port. Choose "Continue Anyway" to install the drivers.



Figure 3 - Installation Warning (first of two warnings)




Figure 4 - Installation Warning (second of two warnings)

Click “Finish” as shown in Figure 5 to complete pre-installation of the drivers.




Figure 5 - Pre-installation of drivers complete

**STEP 2.** Connect the USB-to-serial hardware to the PC. Windows displays the Found New Hardware dialog box (“TUSB3410 device”). Select the “Install the software automatically” option and click on “Next” in Figure 6.



Figure 6 - Found New Hardware (“TUSB3410 Device”)

Once again, choose “Continue Anyway” to install the drivers.



Figure 7 - Hardware Installation Warning (“TUSB3410 Device”)

Click on “Finish” to complete the installation of the device as shown in Figure 8 below.




Figure 8 - Device installation complete.

**STEP 3:** Windows displays the Found New Hardware dialog box (USB-Serial Port). Select the “Install the software automatically” option and click on “Next” in Figure 9



Figure 9 - Found New Hardware (USB – Serial Port)

Once again, choose “Continue Anyway” to install the drivers.



Figure 10 - Hardware Installation Warning (USB-Serial Port)

Click on “Finish” to complete the installation of the USB-Serial port device as shown in Figure 11 below



Figure 11 - USB-Serial port installation complete

The device manager display for a successful installation is shown in the Figure 12 below. Choose My Computer-> Properties -> Hardware -> Device Manager to see this.






Figure 12 - Windows 2K/XP Device Manager

To check the driver version, double click the “TUSB3410 Device” and select the driver tab as shown in Figure 13




Figure 13 - Device Driver Properties

### ***OS: Windows 98SE***

**Step 1:** To install the driver, run setup.exe, located at directory \DISK1 on the installation media. This will install all the necessary files in the default directory C:\Program Files\Texas Instruments. The progress is shown by the following windows.




Figure 14 - Driver installation progress

Click Finish to complete the pre-installation of the drivers




Figure 15 - Driver installation complete

**STEP 2.** Connect the USB-to-serial hardware to the PC. When the system asks for drivers, point to the directory where the drivers were copied.




Figure 16 - Windows98SE New Hardware Found

The device manager display for a successful installation is shown in the Figure 17 below. Choose My Computer-> Properties -> Device Manager to see this.




Figure 17 - Windows 98SE Device Manager

# USB Driver Uninstallation

## ***OS: Windows XP, Windows 2000***

**STEP 1.** To uninstall the drivers, run setup.exe, located at directory \DISK1 of the installation media. Note that when setup.exe is run for the first time, it preinstalls the drivers. Running setup.exe a second time uninstalls all the driver files and cleans up the registry entries that were added during installation.

The uninstaller displays the dialog box shown in Figure 18 below. Select “OK” to uninstall drivers.




Figure 18 - Confirm uninstall

To continue uninstallation, un-plug the device.




Figure 19 - Driver uninstallation

Once the device is unplugged, the uninstaller proceeds to clean up all the files added during installation and the registry entries added during installation.

Click “Finish” to complete uninstallation.




Figure 20 - Uninstallation Complete.